



# TECHNICAL DATA

# TUFFPATCH

# TOP COAT

PRODUCT #710

## PRODUCT DESCRIPTION

**Product #710-TC** is a uniquely formulated 100% solids epoxy coating for industrial use. Designed for a wide variety of applications #710-TC provides an ideal, economical, high-build epoxy used to level and restore deteriorated, or pitted concrete to a smooth and highly durable finish.

**#710-TC** provides excellent adhesion to properly prepared surfaces, and in most cases requires no primer. When cured **#710-TC** provides a smooth glass-like surface that provides excellent abrasion resistance.

## ADVANTAGES

- 100% solids formulation, No VOC's or solvent odor
- Easy to apply
- Provides a durable, long-lasting surface that is easily cleanable
- High-Gloss finish
- Meets USDA requirements
- Economical

## LIMITATIONS

- Do not apply when the temperature is below 45 Degrees F
- Do not apply to surfaces that have not been properly prepared
- Do not apply to damp or wet surfaces

## PACKAGING

Available in 1 gallon or 3-gallon units

Colors Available: Dark Gray, Light Gray, Beige, Tile Red

## COVERAGE

100-160 sq. ft. per gallon is recommended (will vary based on surface porosity)

## PRODUCT APPLICATION

**Surface Preparation:** Concrete must be clean and sound. The surface to be coated should be free of dust, dirt, curing compounds, oils, and any peeling paints or previous coatings. The concrete should be mechanically abraded to allow proper adhesion.

**Mixing:** Combine Part A with Part B and drill or mix for 3 minutes.

**Application:** Pour mixed product in "ribbons" approximately 12"-18" wide and spread with a squeegee, or a high-quality 3/8" nap, non-shed roller cover. Do not leave mixed material in the mixing vessel, by pouring the entire mix onto the surface in "ribbons" working time will be extended. DO NOT TIP THE MIXING VESSEL OVER IN AN ATTEMPT TO GET EVERY LAST DROP OF PRODUCT ONTO THE SURFACE. THERE WILL BE UN-MIXED PARTS A & PART B IN SMALL AMOUNTS THAT DID NOT GET COMPLETELY MIXED.

**Cleanup:** Clean skin with soap and water. Tools and equipment should be cleaned with a general-purpose solvent such as xylene or lacquer thinner.

**Disposal:** Properly dispose of in accordance with local and state regulations.